

ERRATA: P75 mk4 Owner's Manual Correction

The P75 Owner's Manual contains an error in the MM Gain Jumpers JB9, JB10

Documents applicable:

P75 Owner's Manual rev 1.0 and rev 1.1

The error appears in all the diagrams and the switch settings on page 6.

This sheet has the correct settings.

The latest version of the Owner's Manual can be downloaded from:

<http://www.dynavector.com.au/index-4-P75.html>

